



October 2, 2006

Ms. Sue McKay  
Director of Certification  
Election Systems & Software (ES&S)  
11028 John Galt Blvd.  
Omaha, NE 68137

RE: Provisional Certification of ES&S Unity 3.0.1.2 w/ AutoMARK 1.1

Dear Ms. McKay:

The voting system modification identified as ESD&S Unity 3.0.1.2 with AutoMARK 1.1 has been evaluated at an accredited testing laboratory for conformance to the *2002 Voting System Standards*. This provisional certification applies only to the specific version and release of the product in its evaluated configuration and only for the duration of the EAC Interim Certification Program. The evaluation has been verified by EAC Technical Reviewers in accordance with the provisions of the EAC Pre-Election Voting System Certification Program. The review finds that the conclusions of the testing laboratory are consistent with the evidence adduced. This certification is not an endorsement of the product by any agency of the U.S. Government and no warranty of the product is either expressed or implied.

Sincerely,

A handwritten signature in black ink, appearing to read "T. Wilkey".

Thomas R. Wilkey  
Executive Director  
U.S. Election Assistance  
Commission

Attachment

## Attachment 1.

### ES&S Unity 3.0.1.2

Configurations	Hardware & Firmware	Election Management Software
ES&S Unity 3.0.1.2 Voting System- iVotronic with the RTAL printer	iVotronic and Real-Time Audit Log Printer Firmware v.11 iVotronic Firmware v.9.1.6.2	Election Data Manager, v.7.4.4.0 iVotronic Image Manager, v.2.0.1.0 Hardware Programming Manager, v.5.2.5.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0 Data Acquisition Manager, v.6.0.0.0
ES&S Unity 3.0.1.2 Voting System- iVotronic with the Compact Flash Multi-Card Reader/Writer	iVotronic DRE iVotronic Firmware v.9.1.6.2  Compact Flash	Election Data Manager, v.7.4.4.0 iVotronic Image Manager, v.2.0.1.0 Hardware Programming Manager, v.5.2.5.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0

Configurations	Hardware & Firmware	Election Management Software
		Data Acquisition Manager, v.6.0.0.0
ES&S Unity 3.0.1.2 Voting System- iVotronic	iVotronic DRE iVotronic Firmware v.9.1.6.2	Election Data Manager, v.7.4.4.0 iVotronic Image Manager, v.2.0.1.0 Hardware Programming Manager, v.5.2.5.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0 Data Acquisition Manager, v.6.0.0.0
ES&S Unity 3.0.1.2 Voting System- iVotronic with Volume Control Panel	iVotronic DRE iVotronic Firmware v.9.1.6.2	Election Data Manager, v.7.4.4.0 iVotronic Image Manager, v.2.0.1.0 Hardware Programming Manager, v.5.2.5.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0 Data Acquisition Manager, v.6.0.0.0
ES&S Unity 3.0.1.2 Voting System- Optech Image Manager	N/A	Election Data Manager, v.7.4.4.0 Optech Image Manager v.4.0.0.0 Hardware Programming Manager, v.5.2.5.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0
ES&S Unity 3.0.1.2 Voting System- M100	M100 Optical Scanner M100 Firmware v.5.2.1.0 & 5.2.1.1	Election Data Manager, v.7.4.4.0 ES&S Ballot Image Manager, v.7.4.2.0 Hardware Programming Manager, v.5.2.5.0 Ballot On Line v. 1.2.0.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0 Data Acquisition Manager, v.6.0.0.0
ES&S Unity 3.0.1.2 Voting System- M650	M650 Optical Scanner M650 Firmware v.2.1.0.0	Election Data Manager, v.7.4.4.0 ES&S Ballot Image Manager, v.7.4.2.0 Ballot On Line v.1.2.0.0 Hardware Programming Manager, v.5.2.5.0 Audit Manager, v.7.3.0.0 Election Reporting Manager, v.7.1.3.0
ES&S AutoMARK Voting System	AutoMARK Voter Assist Terminal v. 1.0 & 1.1 AutoMARK Voter Assist Terminal firmware v.1.1.2258	Unity 3.0.1.2 Model 100 Optical Scan Precinct Ballot Counter v.5.2.1.0 & 5.2.1.1 Model 650 v.2.1.0.0 Central Count Tabulator